

COP Certificate No.

C	C	0	C	T	1	7	8	6
---	---	---	---	---	---	---	---	---

 [National Automotive Board (NAB)]Date : 30th Sep 2024

Cert	Dwg	Total
1	0	1 pg

CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Name of the Customer :	M/s. Guangdong Dahao Vehicle Accessory Industry & Commerce Co. Ltd.	
2	Address of the Customer:	Factory A, No.101, Zhuhe Road, Haojiang district, Shantou City, Guangdong Province (515098)	
3	Name of the Component Manufacturer :	M/s. Guangdong Dahao Vehicle Accessory Industry & Commerce Co. Ltd.	
4	Address of the Component Manufacturing Plant:	Factory A, No.101, Zhuhe Road, Haojiang district, Shantou City, Guangdong Province (515098)	
5	Manufacturer of:	Safety Belt Assembly	
6	Nomenclature:	3 Point Safety Belt Assembly with ELR for 2 nd Row RH/LH Seats	
7	Part Nos.:	2 nd Row RH Safety Belt Assy.	24323284
		2 nd Row LH Safety Belt Assy.	24323281
8	Applicable for Vehicle Model:	E230R	

Meets all the test requirements as per IS:15140-2018, Amend. 1, Feb 2022 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.

Valid Until: <i>* May change subjected to any further amendment in AIS : 037</i>	30.09.2025
Reference Test Report number(s):	CT0CT1785 dated 30.09.2024
TAC Reference:	TAC No. CN1528 dated 19.12.2022
Previous COP Certificate number :	CC0CS1905 dated 30.09.2023

ICAT Reference	177110	Please turn over for DISCLAIMER	
AUTHORISED SIGNATORY			
AMOL KUMAR Deputy Manager	PRITAM SINGH SAWARIYA Sr. Manager	SAURABH DALELA Director	Page 1 of 1