

## ANNEXURE - I

| Rule No. | Sub Rule(s)                                 | Compliance Verified For  |                                | Standard                        |                                   |
|----------|---|--|--------------------------------|---------------------------------|-----------------------------------|
| 93       | (1)(A), (1)(B) & 2                          | Motor vehicle width, length and height   |                                | -                               |                                   |
| 94       | (1), (2) & (3)                              | Condition of tyres   |                                | -                               |                                   |
| 95       | (1), (2), (3), (4), (5) & (6)<br>(Tubeless) | Size & ply rating of tyres   |                                | IS 15627:2005 &<br>AIS-050:2004 |                                   |
|          |   | Front  | 90/90-12, 54L<br>90/90-12, 54J |                                 | M/s Ralson<br>M/s Ceat<br>M/s TVS |
|          |   | Rear   |                                |                                 |                                   |
| 96       | (1), (2), (3),(4)(ib), (7)(c) & (8)         | Brakes   |                                | IS 14664:2010                   |                                   |
| 102      | (1), (2) & (3)                              | Signaling devices, direction indicators and stop lights  |                                | -                               |                                   |
| 103      | (1)   | Position of the indicator  |                                | -                               |                                   |
| 104      | (1) & (4)                                   | Fitment of reflectors  |                                | AIS-057 (Rev. 1): 2010          |                                   |
| 105      | (1)(bb), (2)(i) & (4)                       | Lamps  |                                | -                               |                                   |
| 106      | (1)   | Deflection of lights   |                                | -                               |                                   |
| 108      | (1)   | Use of red or white lights   |                                | -                               |                                   |
| 111      | -   | Prohibition of spotlights etc.   |                                | -                               |                                   |
| 117      | (1) & (2)                                   | Speedometer  |                                | IS 11827:2008                   |                                   |
| 119      | (1) & (2)                                   | Horns  | Installation (Below 7kW)       |                                 | IS 15796:2008                     |
|          |   |  | Limit :                        | 83 dB(A) to 112 dB(A)           |                                   |
|          |   |  | Observed :                     | 95.3 dB(A)                      | IS 1884:1993                      |
|          |   |  | Performance                    |                                 |                                   |
| 120      | (2)   | Pass by Noise  | Limit :                        | 75 dB(A)                        | IS 3028:1998                      |
|          |   |  | Observed :                     | 59 dB(A)                        |                                   |
| 122      | (1) & (2)                                   | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                                | AIS-065:2005                    |                                   |
| 123      | (1)   | Safety devices in motor cycle  |                                | Pillion Handhold                | IS 14495:1998                     |
|          | (2)   |  |                                | Footrests                       | AIS 148:2018                      |
|          | (4)   |  |                                | Stand                           | AIS 146:2018                      |
|          | (5)   |  |                                | External Projection             | AIS 147:2018                      |
| 124      | Refer Annexure-IA & IB                      | Safety standards of components as applicable   |                                | -                               |                                   |
| 125      | (2)(a)                                      | Rear View Mirror   | Specifications                 |                                 | AIS-001 (Part 2) (Rev.1):2011     |
|          |   |  | Installation                   |                                 | AIS-002 (Part 2) (Rev.1):2011     |

|                       |                             |
|-----------------------|-----------------------------|
| ICAT Ref No.          | 2024-0403; IOCS Ref: 177357 |
| Power Test Report No. | CTOPT 0570 Dt. 12.08.2024   |
| Noise Report No.      | CTOVT 01387 Dt. 10.09.2024  |
| Horn Inst. Report No. | CTOVT 01386 Dt. 10.09.2024  |

| AUTHORISED SIGNATORY                 |                                   |                |
|--------------------------------------|-----------------------------------|----------------|
|                                      |                                   |                |
| <b>JAYWANT HARDIKAR</b><br>HEAD-CMVR | <b>SAURABH DALELA</b><br>DIRECTOR | Page 2 of<br>4 |