

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/ Rear	1. 90/90 -12, 64B 2. 3.75-12, 60J 3. 3.75-12, 66B 1. RALSON 2. TVS 3. CEAT	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3)	Safety glass		NA
101	(1)	Windscreen Wiper		NA
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 96.4 dB(A) & 101.05 dB(A)	
			Performance	IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2)Rev.1:2011
			Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2024-1805 (182913)		
Power Test Report No.	CT0ER 0499 dt. 08.12.2022		
Horn Inst. Report No.	CT0VT 0106 dt. 31.01.2024		
AUTHORISED SIGNATORY			
JAYWANT HARDIKAR HEAD-CMVR		SAURABH DALELA DIRECTOR	
			Page 2 of 3