

## ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), & (2)	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/ Rear	90/90-12 54J		Make TVS Srichakra  CEAT
96	(1), (2), (3), (4)(ib), (4A), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008
			Limit :	87 dB(A) to 112 dB(A)	
			Observed :	92.7 dB(A)	Performance
120	(2)	Pass by Noise	Limit :	75 dB(A)	IS 3028:1998
			Observed :	73 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold		IS 14495:1998
	(2)		Footrests		AIS 148:2018
	(4)		Stand		AIS 146:2018
	(5)		External Projection		AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications		AIS-001 (Part 2) (Rev.1):2011
		Mirror	Installation		AIS-002 (Part 2) (Rev.1):2011

<b>ICAT Ref No.</b>	2024-1831 (IOCS Ref: 183291)
<b>Power Test Report No.</b>	GTTN 00058 dt. 28.11.2024
<b>Noise Report No.</b>	CT1VU 0134 dt. 21.01.2025
<b>Horn Inst. Report No.</b>	CT0VS 1176 dt. 21.07.2023

AUTHORISED SIGNATORY			
<b>JAYWANT HARDIKAR</b> <b>HEAD-CMVR</b>		<b>SAURABH DALELA</b> <b>DIRECTOR</b>	Page 2 of 4