

## ANNEXURE - I

| Rule No. | Sub Rule(s)                   | Compliance Verified For  |                | Standard                     |
|----------|-------------------------------|--|----------------|------------------------------|
| 93       | (1)(A), (1)(B), (2)           | Motor vehicle width, length and height   |                | -                            |
| 94       | (1), (2), (3)                 | Condition of tyres   |                | -                            |
| 95       | (1), (2),(3), (4), (5) & (6)  | Size & ply rating of tyres   |                | IS 15627:2005 & AIS-050-2004 |
|          |                               | Front/<br>Rear   | Make           |                              |
| 96       | (1), (2), (3), (4)(i), (7)(b) | Refer Annexure - IV  |                | IS 14664:1999                |
| 99       | -                             | Brakes   |                | IS 14664:1999                |
| 100      | (1), (2), (3-A) & (3)(c)      | Forward and backward motion  |                | -                            |
| 101      | (1)                           | Safety glass   |                | NA                           |
| 102      | (1)                           | Windscreen Wiper   |                | -                            |
| 103      | (1), (2)                      | Signaling devices, direction indicators and stop lights  |                | -                            |
| 104      | (1)(v),(4)                    | Position of the indicator  |                | -                            |
| 105      | (1)(b), (3), (4), (5), (7)    | Fitment of reflectors & reflective tapes   |                | AIS-057-2005 & AIS-090-2005  |
| 106      | (1)                           | Lamps  |                | -                            |
| 108      | (1)                           | Deflection of lights   |                | -                            |
| 109      | -                             | Use of red or white lights   |                | -                            |
| 110      | -                             | Parking lights   |                | -                            |
| 111      | -                             | Lamps for three wheelers   |                | -                            |
| 119      | (1) & (2)                     | Horns  | Installation   | IS 15796:2008                |
|          |                               |  | Limit :        |                              |
|          |                               |  | Observed :     | 91.1 dB(A)                   |
| 122      | (1) & (2)                     | Performance  |                | IS 1884:1993                 |
| 124      | (1) & (2)                     | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                | AIS-065-2005                 |
| 125      | -                             | Safety standards of components as applicable   |                | Refer ANNEXURE - IA & IB     |
| 125      | (2)(a)                        | Rear View<br>Mirror  | Specifications | AIS-001 (Part-2)Rev.1:2011   |
|          |                               |  | Installation   | AIS-002 (Part-2)Rev.1:2011   |

|                       |   |
|-----------------------|---|
| ICAT Ref No.          | 2024-0558 (IOCS No.178325)                          |
| Power Test Report No. | CT0ET 0069 dt.23.02.2024 & CT0PT 0696 dt 16.10.2024 |
| Horn Inst. Report No. | CT0VT 1514 dt.24.09.2024                            |

| AUTHORISED SIGNATORY          |                            |                |
|-------------------------------|----------------------------|----------------|
|                               |                            |                |
| JAYWANT HARDIKAR<br>HEAD-CMVR | SAURABH DALELA<br>DIRECTOR | Page 2 of<br>4 |